

Hardware - Tickets

#	Tracker	Status	Priorität	Thema	Zugewiesen an	Aktualisiert
718	Fehler	Neu	Normal	Calculate voltage-divider for "Enable" MOSFETS	Maximilian Seesslen	11.12.2025 13:29
716	Fehler	Neu	Normal	Driver board: No level shifter for I2C	Maximilian Seesslen	02.12.2025 15:16
707	Feature	Neu	Normal	Housing	Maximilian Seesslen	04.11.2025 11:08
706	Fehler	Neu	Normal	One pin is completely missing	Maximilian Seesslen	04.11.2025 11:03
495	Unterstützung	Neu	Normal	Are both wakeups working correctly	Maximilian Seesslen	23.02.2024 13:22
494	Unterstützung	Neu	Normal	Does UART-RX need Pullu por -down?	Maximilian Seesslen	23.02.2024 13:21
471	Fehler	Neu	Niedrig	Wakeup-Button is not working	Maximilian Seesslen	05.02.2024 22:54
426	Fehler	Neu	Normal	Footprint fuer thermocouple-Kupplung hat fehler	Maximilian Seesslen	15.09.2023 11:28
425	Feature	Neu	Normal	PCB: missing info for 3V	Maximilian Seesslen	12.09.2023 12:03
421	Feature	Neu	Normal	Create sinewave for DAC/DMA	Maximilian Seesslen	28.08.2023 18:52
388	Feature	Neu	Normal	use bigger buttons	Maximilian Seesslen	27.03.2023 14:24
327	Fehler	Neu	Normal	Power consumption too high	Maximilian Seesslen	09.01.2023 13:26
290	Fehler	Neu	Normal	Yellow and red LEDs are quite dark	Maximilian Seesslen	26.10.2022 14:38
271	Fehler	Neu	Normal	consumption tests completely missing	Maximilian Seesslen	14.10.2022 15:57
233	Feature	Neu	Normal	Switch via photodiode	Maximilian Seesslen	11.12.2022 17:39
210	Fehler	Neu	Normal	PCB routing problem	Maximilian Seesslen	01.02.2024 14:27
187	Unterstützung	Neu	Normal	Bringup HW v0.2.x	Maximilian Seesslen	24.01.2023 13:59
135	Unterstützung	Neu	Normal	Create BOM creator script with warehouse fields	Maximilian Seesslen	13.01.2022 15:30
32	Fehler	Neu	Normal	Move the notes from "warehouse" to redmine.	Maximilian Seesslen	13.08.2021 12:56